

# ABSTRACT

A method of starting a nickel metal hydride battery in cold weather. The method includes the step of discharging  
5 the battery through a short circuit.